

 <b>National Transportation Safety Board</b> <b>FOREIGN NOTIFICATION</b> <b>AVIATION</b>		NTSB ID: DCA11RA097		Most Critical Injury:	
		Occurrence Date: 08/20/2011		Investigated By: Foreign	
		Occurrence Type: Accident			
Location/Time					
Nearest City/Place Resolute		State	Zip Code	Local Time 1230	Time Zone CDT
Aircraft Information					
Registration Number CGNWN		Aircraft Manufacturer BOEING		Model/Series Number 737/200	
Type of Aircraft: Airplane			Amateur Built Aircraft? No		
Injury Summary:		Fatal	Serious	Minor	None
Revenue Sightseeing Flight:			Air Medical Transport Flight:		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>*** Note: The foreign authority was the source of this information. ***</p> <p>On August 20, 2011, about 1230 central daylight time (local), a Boeing 737-200, Canadian registration CGNWN, operated by First Air in a combination passenger/freight configuration as flight 6560 and equipped with Pratt &amp; Whitney JT8D engines, impacted terrain approximately 1 mile east of the airport while on approach for landing at Resolute Bay Airport, Resolute, Nunavut, Canada. Of the four crew and eleven passengers, twelve occupants were fatally injured.</p> <p>The Transportation Safety Board (TSB) of Canada is investigating the accident. As the state of manufacture of the airplane and engines, the NTSB has designated a U.S. Accredited Representative to assist the TSB in their investigation.</p> <p>All inquiries concerning this accident should be directed to the TSB of Canada at:</p> <p>Transportation Safety Board of Canada  200 Promenade du Portage  Place du Centre, 4th Floor  Hull, Quebec K1A 1K8  Canada</p> <p>Website: <a href="http://www.tsb.gc.ca">http://www.tsb.gc.ca</a>  Updated on Aug 22 2011 2:33PM</p>					
FOREIGN INFORMATION - SUBJECT TO CHANGG					